STOK) WAKA 110

## PRESENT CONDITIONS OF THREE SELECTED FISHERY HABOURS OF SRI LANKA

THE CASE OF THOSE SELECTED PUBLIC OF MAN LAND

TANKALI E GOLLE ON SERVICE


- TANGALLE, GALLE AND BERUWALA -

THE PARKS CO. OF CANADA PROPER PARKS OF

PRESENT CONDITIONS OF THREE SELECTED FISHERY HARBOURS OF SRI LANKA
- TANGALLE, GALLE AND BERUWALA -

## S. Y. NAMARATNE HEMANTHA DASSANAYAKE

NATIONAL AQUATIC RESOURCES AGENCY
CROW ISLAND
MATTAKKULIYA
COLOMBO 15
SRI LANKA.



REPORT SUBMITTED TO BOBP/IMO/NARA BY THE NATIONAL CONSULTANTS OF SRI LANKA FOR THE CLEANER FISHERY HARBOURS PROJECT, OCTOBER 1991.

Dr. W. D. N. Wickramaarachchi Senior Scientist Environmental Studies Division National Aquatic Resources Research and Development Agency

## CONTENTS

		Page No
1.		01
2.	Tangalle Fishery Harbour	
3.	Galle Fishery Harbour	19
4.	Beruwala Fishery Harbour	
5.	Cost estimates for improvements of the harbours	
	List of contacts	50